

Installation and usage recommendations for Gigantic Color's Static Cling material

- Gigantic Color's removable static cling material may be applied to a variety of smooth, polished surfaces such as glass, plastic, chrome and high gloss smooth painted surfaces.
- Gigantic Color's static cling vinyl material is designed for indoor or outdoor use only. (Note that you can use this material for a window graphic placed on the interior of the window but is viewable from the exterior of the window).
- Do not use product in areas where the temperature is below 32 degrees F or above 150 degrees F.
- For best results, application surface and static cling material should be 32 degrees F or above when graphics are being applied.
- Gigantic Color's static cling material is not recommended for graphics larger than 20" x 20".
- For proper adhesion, the surface must be clean and dry. Note that the material will not adhere properly to grease, oil or dirt.
 - To clean/prepare a glass surface before installation, use an ammonia-based window cleaner. Do not use silicone based cleaners.
 - To remove grease and/or oil on a non-glass surface, use mineral spirits, heptanes or V.M. & P naphtha. Once this step is complete, clean surface with a combination of warm water and a small amount of mild soap or detergent. Wipe surface with a clean, soft, lint free cloth. Allow surface to air dry completely before installing cling.
 - Note that cling material cannot be applied to a freshly painted high gloss surface. Please allow the painted surface time to air dry for a minimum of one week prior to installation.
- A wet application method is required for installation. Steps for a wet application:
 - Prepare a wetting solution of two teaspoons of liquid household detergent in one gallon of cold water.
 - Remove cling from the release liner and lay face down on a clean, flat surface (Note that the "face" of the cling is NOT the side that the release liner was removed from).
 - Mist the application surface with the wetting solution. This is most easily accomplished by spraying the wetting solution directly onto the application surface.
 - Place the cling in contact with the application surface. Note that the side of the cling that should be adhered is the side that the release liner was removed from. The wetting solution will allow the cling to be slid across the application surface for positioning purposes.
 - Once the cling is in the correct position, squeegee the water out by gently working from the center of the cling to the edges. Note that you can use a rubber roller or a felt faced squeegee.
 - Use paper towels to blot any excess moisture. Gently apply pressure to the edges to ensure the clings have adhered properly.
- Gigantic Color's cling material can be easily removed and can be reused. Clings must be stored on the release liner (application side should be placed on the release liner) in a clean, dry environment.
- When reusing a static cling, if adhesion seems low, dip cling in warm water to increase adhesion and then apply to surface.



GIGANTICCOLOR

giganticcolor.com